



US005425165A

United States Patent [19][11] **Patent Number:** **5,425,165**

Shramo et al.

[45] **Date of Patent:** **Jun. 20, 1995**[54] **METHOD OF MAKING A SLOTLESS, BRUSHLESS, LARGE AIR-GAP ELECTRIC MOTOR**[76] **Inventors:** Daniel J. Shramo; Susan M. Benford,
both of 20791 Avalon Dr., Rocky
River, Ohio 44116[21] **Appl. No.:** 42,119[22] **Filed:** Apr. 2, 1993**Related U.S. Application Data**[60] Division of Ser. No. 776,724, Oct. 15, 1991, Pat. No.
5,200,661, which is a continuation of Ser. No. 451,810,
Dec. 15, 1989, abandoned.[51] **Int. Cl.⁶** H02K 15/04[52] **U.S. Cl.** 29/596; 29/598;
29/605[58] **Field of Search** 29/598, 605, 596;
360/42, 43, 266, 268[56] **References Cited****U.S. PATENT DOCUMENTS**

847,008 3/1907 Kitsec .
 2,903,610 9/1959 Bessiere .
 2,930,916 3/1960 Scanlon .
 3,441,761 4/1969 Painton et al. 29/598 X
 3,831,267 8/1974 Onishi et al. 29/598
 3,883,633 5/1975 Kohler .
 3,956,651 5/1976 Brammerio .
 3,968,390 7/1976 Yasuda .
 3,983,433 9/1976 Sims .
 3,983,435 9/1976 Sims .
 4,130,769 12/1978 Karube .
 4,156,168 5/1979 Vogel .
 4,292,558 9/1981 Flick et al. .
 4,292,559 9/1981 Auinger .
 4,355,255 10/1982 Herr .
 4,392,072 7/1983 Rosenberg .


4,446,393 5/1984 Finegold .
 4,472,666 9/1984 Akeda et al. .
 4,473,752 9/1984 Cronin .
 4,499,408 2/1985 Bitting .
 4,528,485 7/1985 Boyd, Jr. .
 4,563,808 1/1986 Lender .
 4,564,777 1/1986 Senoo .
 4,594,523 6/1986 Horita .
 4,645,961 2/1987 Malsky .
 4,665,331 5/1987 Sudo et al. .
 4,703,211 10/1987 Yazaki et al. .
 4,774,428 9/1988 Konecny .
 4,937,485 6/1990 Mihalko .
 5,001,375 3/1991 Jones .
 5,197,180 3/1993 Mihalko 29/598 X

Primary Examiner—Carl E. Hall**Attorney, Agent, or Firm**—Renner, Otto, Boisselle &
Sklar

[57]

ABSTRACT

A slotless brushless, large air gap electric motor comprises a stator having a field winding and field backiron, the field winding being composed of a plurality of successively offset polygonal shaped turns so as to provide a substantially flat winding, and a rotor disposed within the stator including a shaft with a permanent magnet mounted thereon. The field winding turns are preferably in the shape of a rectangle or a hexagonal. Also disclosed is a commutation scheme which dissipates energy stored in a section of the field winding previously energized to the section of the field winding subsequently energized; an integrated circuit for control of any motor using that commutation scheme; a winding configuration suitable for use with both an alternating and direct current power supply; and efficiency increasing magnetically permeable flux shorting elements.

20 Claims, 7 Drawing Sheets




FIG. 1




FIG. 2




FIG. 3




FIG. 4

back iron

back iron core

magnet




FIG. 5




FIG. 6




FIG. 8




FIG. 7




FIG. 9




FIG. 15




FIG. 14








FIG. 13








FIG. 17





FIG. 19




FIG. 20

METHOD OF MAKING A SLOTLESS, BRUSHLESS, LARGE AIR-GAP ELECTRIC MOTOR

This is a divisional of application Ser. No. 07/776,724 filed on Oct. 15, 1991, now U.S. Pat. No. 5,200,661, which is a continuation of application Ser. No. 07/451,810 filed on Dec. 15, 1989, now abandoned.

FIELD OF THE INVENTION

The invention relates generally to electromechanical devices such as electrical motors, generators and the like and, more particularly to slotless, brushless, large air-gap electrical motors.

BACKGROUND OF THE INVENTION

Slotless, brushless, large air-gap electric motors are well known and used in a variety of applications. These applications include use in power tools, consumer appliances, and the automotive industry to name but a few.

Due to the nature of this type of motor, for different applications, the motor must be substantially redesigned to provide the desired torque and horsepower. Additionally, a different electronics package ordinarily would be necessary to control each different motor. As a result of these factors and the difficulty of manufacturing slotless, brushless motors, the motors become a major cost factor for many of the items in which they are employed or in which it would be desirable to employ them. An example is in the power tools or appliances mentioned above. Consequently, reducing the cost of the motor in these and other appliances and applications would greatly impact the overall cost of the complete item. Moreover, in large, high volume applications for such motors, e.g., in the automobile industry, although the cost of one or even a few motors may not contribute significantly to the cost of an item, say an automobile, the overall motor cost as a result of volume would be significant and a reduction of that cost would be advantageous.

Slotless, brushless, large air-gap motors also are relatively inefficient. Some inefficiencies are due to hysteresis and eddy current losses as well as other losses that typically are dissipated as heat. Another exemplary inefficiency is the limitation on use with only one type of input electrical energy, namely either from a direct current or an alternating current power supply. Improving the efficiency of such motor and permitting its use with both types of power supplies interchangeably, would allow the motors to more readily be used in general and would expand the market for such motors. For instance, it would be desirable for such a motor to be used in an appliance, such as a hand drill, that would be able to run less hot than a conventional hand drill and that also either could be plugged into a wall outlet or alternatively could be powered by a battery pack.

SUMMARY OF THE INVENTION

The invention relates to improvements in slotless, brushless, large air gap motors. Such improvements concern efficiency of operation, ease of manufacturing, and versatility. The invention also relates to a commutation scheme and to a versatile electronic control package that can be used to control several (preferably any) motors designed in accordance with the commutation scheme of the invention, regardless of torque and horsepower characteristics.

Accordingly it is an object of the present invention to provide a high efficiency slotless, brushless, large air-gap motor.

It is another object of the present invention to simplify and to reduce the cost of manufacture of such a motor by automating the manufacture and employing a unique coil winding configuration.

Another object is to minimize the amount of coil wiring necessary to drive the motor.

Another object is to provide a commutation scheme that allows a common set of control electronics to be used for any size motor, which permits the control electronics to be an integral part of the motor assembly.

A further object is to provide a variable speed motor in which the speed is determined by modulating the pulse width of the applied power.

In accordance with one aspect of the present invention a slotless, brushless, large air-gap electric motor includes a stator having a field winding and field backiron; the field winding having a number of successively offset polygonal shaped turns so as to provide a substantially flat winding; and a rotor disposed within the stator including a shaft and a permanent magnet mounted thereon. The polygonal shaped turns may be in the shape of a rectangle or a hexagonal, for example.

In accordance with another aspect, a method of making a field winding for an electrical motor includes the steps of spirally winding a wire around a polygonal shaped form; leaving a space at predetermined distances, such space having a length of such predetermined distance; collapsing two opposite sides of such form so that the wire winding will substantially flatten to fill the empty spaces with successively offset turns of such winding having the approximate polygonal shape; and wrapping the flattened winding to form a hollow cylinder.

In still another aspect of the invention an electric motor includes a stator having a field winding and a field backiron, the field winding configured in a Wye with a commutation switch between each leg of the Wye and ground and a power switch between the common juncture of such Wye and a power supply; a rotor disposed within the stator including a shaft and a permanent magnet mounted thereon; and an integrated circuit controlling said switches.

In addition, according to another aspect, an electric motor includes a stator having a field winding and field backiron, and a rotor disposed within the stator including a shaft, a permanent magnet mounted thereon, and a pair of elements located on either side of the permanent magnet to complete a magnetic circuit between opposite poles of the permanent magnet.

According to another aspect of the invention a polyphase electric motor includes a stator having a field winding and a field backiron, the field winding configured in a Wye with a switch between each leg of the Wye and ground and a switch between the common juncture of such Wye and a power supply; and a rotor disposed within the stator including a shaft and a permanent magnet mounted thereon.

In addition, according to a further aspect, an electric motor includes a stator having a field winding and a field backiron, the field winding having sections for energizing by both rectified alternating current and direct current, and sections for energizing by rectified alternating current alone; and a rotor disposed within the stator including a shaft and a permanent magnet mounted thereon.

According to still another aspect of the invention a method of commutating a polyphase electrical motor includes the steps of sequentially applying power to a first field winding phase; interrupting power to the first field winding phase; dissipating energy stored in the first winding phase to a second winding phase; and applying power to said second winding phase.

These and other objects, advantages, features and aspects of the present invention will become apparent as the following description proceeds.

To the accomplishments of the foregoing and related ends, the invention, then, comprises and features hereinafter fully described in the specification and particularly point out in claims, the following description and the annexed drawings setting forth in detail a certain illustrative embodiment of the invention, this being indicative, however, of but one of the various ways in which the principals of the invention may be employed. It will be appreciated that the scope of the invention is to be determined by the claims and the equivalents thereof.

BRIEF DESCRIPTION OF THE DRAWINGS

In the annexed figures:

FIG. 1 is an illustration of a slotless, brushless, large air gap motor according to the present invention;

FIG. 2 is an end view of the motor showing the closed end looking in the direction of arrows 2—2 of FIG. 1;

FIG. 3 is a plan view of the electronics package of the present invention;

FIG. 4 is a cross-sectional view of the motor looking in the direction of arrows 4—4 of FIG. 1;

FIG. 5 is an illustration of the magnetic fields at both ends of a typical permanent magnet rotor;

FIG. 6 is an illustration of the magnetic fields at both ends of the rotor using a magnetic permeable element of the present invention;

FIG. 7 is an oblique view of the coil winding of the present invention wound around a form;

FIG. 8 is an illustration of an exemplary coil phase winding of the present invention wired in series;

FIG. 9 is an illustration of an exemplary coil phase winding wired in parallel;

FIG. 10 is a plan view of the coil winding illustrating the phase configuration;

FIG. 11 is a partially collapsed view of the coil winding;

FIG. 12 is an illustration of the coil winding as it would be wrapped around a cylindrical core;

FIG. 13 is a cross-sectional view of one segment of each phase of the coil winding;

FIG. 14 is a cross-sectional view of the complete coil winding and permanent magnet stator;

FIG. 15 is an illustration of an alternate embodiment of a coil wrapped around a hexagonal winding form for use in the motor of FIG. 1;

FIG. 16 is a schematic electrical circuit diagram of the motor and control circuitry of the present invention;

FIG. 17 is a schematic view of the commutation section of the circuit of FIG. 16;

FIG. 18 is a diagram of the relative phase excitations of the respective coil sections and the supply power as a function of the angular position of the rotor of the motor of FIG. 1;

FIG. 19 is a diagram of the pulse width modulation scheme of the present invention;

FIG. 20 is a schematic electrical circuit diagram of the commutation scheme and power supply of an alter-

nate embodiment of the present invention suitable for use with DC or AC power.

DETAILED DESCRIPTION OF THE INVENTION

With reference to the several figures in which like reference numerals depict like items and initially to FIGS. 1-4, there is shown a slotless, brushless, large air-gap electric motor 10 in accordance with the invention. The motor 10 includes a permanent magnet rotor assembly 12 and a wound stator 14 as is conventional in slotless, brushless motors. The rotor assembly 12 includes an elongate shaft 16 surrounded by a backiron core 18 which is, in turn, surrounded by a permanent magnet 20. The stator assembly 14 includes a coil winding 22 having an inner diameter to provide a space sufficiently large for the rotor to be disposed therein, and a field backiron 24 surrounding the coil winding. The area between the permanent magnet 20 and the inner diameter of the field backiron 24, partially filled by the coil winding 22, is referred to as the air gap 25.

The motor 10 further includes a housing assembly 26 having an open end section 28, middle section 30, and closed end section 32 for housing of the rotor and stator assemblies 12 and 14, respectively. The stator assembly 14 is fixed within the housing assembly 26 while the rotor assembly 12 is mounted so as to permit rotation around its longitudinal axis Z. The rotor assembly 12 is radially and axially fixed within the housing assembly 26 by a pair of bearings 34a, 34b mounted in the open and closed end housing sections 28, 32. Consequently, the rotor assembly 12 is free to rotate within the stator assembly 14. The rotor shaft 16 extends through the open end housing section 28 for attachment to a load, and the effectuation of relative rotation of that load.

A thermally conductive end member 38 in contact with the closed end housing section 32 forms the end closure of the motor 10 and seals the motor from contamination. The end member 38 is provided with a number of terminals 41 and 42 (FIG. 2), for connection to the power supply and motor control inputs, respectively. Mounted to the inward face of the end member 38 and electrically connected to the terminals 41 and 42 is a printed circuit board 44 (FIGS. 1 and 3) upon which is mounted the control electronics (designated generally at 46) of the motor 10. The circuit board 44 preferably is composed of a thin Kapton substrate upon which circuit paths and mounting pads have been printed using well known methods. The control electronics circuit elements such as integrated circuits, transistors, Hall effect sensors, etc. are electrically and mechanically connected to the circuit board 44 using a standard lead bonding or similar technique. An electromagnetic interference (EMI) shield 47 (indicated by a dashed line) may be placed between the circuit board 42 and the rotor and stator assemblies 12, 14 to reduce the deleterious affects of electrical noise on the control electronics.

When running, the majority of heat generated within the motor 10 is from the stator assembly 14. To maintain the operating efficiency of the motor 10 and the reliable functioning of the electronics 46, it is beneficial to transfer the heat generated by the stator assembly 14 away from the rotor 12 and the electronics. Consequently, the housing sections 28, 30 and 32 are made of a material with a high coefficient of thermal conductivity. Also, by mounting the printed circuit board 44 directly to the thermally conductive end member 38, heat generated

by the electronics 46 is effectively transferred to the end member. The end member 38 is preferably designed with fins 40 or other configurations which promote heat transfer to the surrounding environment further helping to maintain relatively cool operation of the electronics 46.

As is shown in FIG. 4, the permanent magnet 20 of the rotor 12 is divided into a number of sections 46, called pole segments, alternatively arranged with opposite magnetic poles, north and south, facing generally in a radially outward direction. In the preferred embodiment three pole pairs, or six magnet sections, are employed. The permanent magnet 20 may be constructed of six generally wedge-shaped separate magnet sections secured together or of a suitable material which may be magnetized appropriately by methods known in the art.

As referenced herein the permanent magnet 20 includes any material(s) or construction of material(s) which will produce a pole-to-pole magnetic field as described below. Also, it will be appreciated that while the following discussion is made with reference to a permanent magnet having three magnetic pole pairs, fewer or more magnetic pole pairs may be employed. For example, the invention may be used with a permanent magnet having 50 pole pairs or more, such as is typical in a stepper motor, or in a motor requiring a permanent magnet having only two pole pairs. Further, it will be appreciated that as used herein the phrases field winding, coil winding and coil are equivalent phrases denoting the element or elements of the stator that produce the stator magnetic field.

The opposite magnetic poles of the permanent magnet 20 create a pole-to-pole magnetic circuit, a portion of which is indicated generally at 48. Magnetic flux emanates from the northern pole faces 50 of the magnet 20 through the air gap 25 and the coil winding 22 to the field backiron 24 where it follows a generally arcuate path towards a southern pole face region. The magnet flux then passes back through the winding 22 and air gap 25 to the southern pole faces 52 and then through the rotor backiron 24 and back to the emanating pole faces 50.

When a current is appropriately applied to the coil winding 22 of the stator 14, a magnetic field is created which interacts with the pole-to-pole field created by the permanent magnet 20 of the rotor 12 to produce a reactant torque between the stator and the rotor. Since the rotor 12 is mounted in the bearings 34a and 34b it is free to rotate and will rotate a distance approximately equal to the arcuate length of two magnet pole faces 50, 52, or 120 degrees, to relieve the torque. As the rotor 12 rotates that distance, the current flow through the coil winding 22 is commutated to provide the next phase of rotation. For a three-phase motor the current must be sequentially applied to three different segments of the coil winding, called coil phases, to cause the rotor to rotate 360 degrees. Continually applying current to the coil phases sequentially accomplishes the continued rotation of the rotor.

The torque and horsepower characteristics of the motor 10 are determined by the reactive strengths of the magnetic fields created by the coil winding 22 and the permanent magnet 20. In general, the magnetic field strength generated by the coil 22 is a function of the number of coil turns and the amount of current flowing through the coil. The magnetic field strength of the permanent magnet 20 is a function of the size of the magnet and the type of material employed. The motor

torque can thus be increased by adding coil turns, raising the current, using a larger permanent magnet, etc. However, the torque characteristics of the motor 10, and thus the efficiency of the motor can also be improved by eliminating magnetic flux losses through the various components of the motor so that the magnetic field interaction between the rotor 12 and the stator 14 is increased.

When the permanent magnet 20 rotates, a fluctuating magnetic field is produced in nearby stationary conductive motor elements, such as the field backiron 24, the bearings, 34a, 34b and the housing assembly 26. This fluctuating field is susceptible to losses attributable to hysteresis and eddy current flows. These losses can be reduced in the field backiron 24 by constructing it of wound flyers or bundles of high permeability magnetic wire having a small cross-sectional area, as more fully described in copending U.S. patent application Ser. No. 07/453,616, filed Dec. 20, 1989, entitled Magnetic Flux Return Path for an Electrical Device which is hereby incorporated by reference. The small cross-sectional area of each wire reduces eddy current flows within the wire and minimizes skin effects associated with high frequency alternating current and harmonics thereof. The field backiron 24 can be manufactured using a conventional winding machine such as is used in producing field windings for conventional slotted electrical motors.

While it is necessary that the fluctuating magnetic field pass through the field backiron 24 to complete the magnetic circuit of the rotor 12, there are other components affected by the magnetic field that result in flux losses but produce no benefits, such as the bearings 34a, 34b and housing end sections 28, 32. Referring to FIG. 5, there is shown a four pole permanent magnet rotor 52 which may be used in a typical slotless, brushless motor. At either end of the magnet 54 there is illustrated diagrammatically a magnet flux circuit 56 established between the northern and southern magnetic poles of the permanent magnet 54 (represented in the figure by phantom lines). As the magnet 54 rotates, this field 56 passes through stationary conductive motor elements such as the bearings, etc., producing a fluctuating field in these elements with the associated hysteresis and eddy current losses.

According to the invention, such losses can be reduced by using a magnetically permeable flux shorting element 58 properly positioned with respect to the rotor 52 in the manner shown in FIG. 6. Placing a high magnetically permeable element 58, such as a soft iron washer, on the rotor magnetically at either end (or both ends) of the magnet 54 shorts the magnetic flux circuit 52 and greatly reduces such losses. As is illustrated in FIG. 6, the magnetic flux 60 will be confined to the washer 58 which, since it is moving with the rotor 52, will have a constant flux. Since the flux is constant and confined in the washer, the field produced by that flux also is constant; therefore, the losses associated with a fluctuating field in general and with a fluctuating field in the bearings 34a, 34b and having end sections 28, 32 in particular will not occur.

These improvements in reducing flux losses increase the strength of the rotor pole-to-pole magnetic field and correspondingly increase the reactant torque with the magnetic field of the coil winding. Since flux losses are dissipated as heat, reducing the losses will allow the motor to run cooler.

Turning now to FIGS. 7-15, features of a preferred coil structure according to the invention are illustrated and described. Initially, referring to FIG. 7, the first step for making a coil winding or field winding for the motor 10 is shown. Such coil winding may be used for one of the phases of the motor 10, for example, the first phase 01 for a three phase motor. In FIG. 7, that first step employs a continuous conductor 61, such as an insulated copper wire, which is wound on a wiring form 62. The wiring form 62 is preferably of a rectangular shape. The form 62 has a height L_M which corresponds to the axial length (direction of motor axis Z) of the permanent magnet 20 and a width L_{R1} which corresponds to the circumferential, or arcuate, length of one section 46, or pole face 50, 52 of the permanent magnet.

Initially, a wire 61 suitable for use in a coil winding, such as a small diameter insulated copper wire, is wrapped around the form 62 to establish plural coil segments, such as the three coil segments A₁, B₁, C₁. The number of coil segments corresponds to the number of pole pairs of the motor 10. In wrapping the wire 61 the first turn 63 made is in the shape of a rectangle having a height L_M and a width L_{Rn} , the dimensions of which correspond to the shape of the form 62. (The subscript "n" as used herein represents a coil phase designation; for example, for coil phase 01, L_{Rn} would represent L_{R1} , and so forth for the other coil segments.) The wire 61 is continually wrapped around the form 62 with each added turn of wire forming an additional adjacent rectangle. This operation is repeated until the cumulative length of the adjacent wire turns (beginning at turn 63a and ending at turn 63b) is also equal to L_{R1} , thus completing the first coil section A₁ of coil phase 01. The next coil turn 64a is then begun spaced over a distance L_{R1} from turn 63b of coil segment A₁ to start the second coil segment B₁. The balance of coil segment B₁ is formed by wrapping multiple turns of the wire 61 around the form 62 ending at turn 64b. Coil segment C₁ is similarly made at a spacing L_{R1} from coil segment B₁. Thus, three equally spaced coil segments, A₁, B₁ and C₁, each of length L_{R1} and each spaced from the adjacent one a distance L_{R1} , are made. These three coil segments A₁, B₁ and C₁ together with the spaces therebetween and the space L_{R1} which also follows the last coil segment C₁ collectively will be used to form one phase of the coil winding 22 (such as that denoted as the first phase 01) having a total length of six times L_{R1} .

The process as explained above for wrapping the first phase 01 of the coil winding 22 is similarly carried out to wrap the second and third phases, 02 and 03, respectively. However, in winding the second and third coil phases, the length and width of the respective coil segments, A_n, B_n and C_n, thereof and the space therebetween will be increased to correspond to the increased arcuate length (at increased radial distance from the motor axis Z) which each subsequent phase of the coil winding 22 must follow when installed in the motor 10, as is explained more fully below. Consequently the width L_{Rn} of the winding form 62 is increased at intervals that correspond to locations at which the respective longer length coil phases are to be wound thereon. In the preferred embodiment, all phases of the coil winding 22 are wound on a single form 62 continuously with appropriate lengths of coil wire tapped to make the necessary circuit connections for each coil segment, A_n, B_n and C_n, of each phase of the coil. Alternatively, each coil segment may be wound on separate respective forms 62 which have appropriate size characteristics.

FIGS. 8 and 9 show exemplary wiring configurations for representative coil turns that form the coil segments of one phase of the coil winding 22 as it would be seen when it is activated or electrically energized as when receiving electric energy. Referring first to FIG. 8 the coil phase shown is electrically connected in series. The first coil segment A_n of wire wound to form the phase is tapped and connected to the power supply V, and the wire continues unbroken until it reaches the end of the phase winding where it is tapped and attached to ground. A parallel configuration for representative coil turns forming the coil segments of one phase of the coil winding 22 is shown in FIG. 9. The wire at the beginning of each phase segment A_n, B_n and C_n is tapped and connected to the power supply V, and the last wire wrapping for each coil segment is tapped and connected to ground. In the latter configuration each coil segment A_n, B_n and C_n is actually a separate circuit or is connected as a separate circuit. Each coil phase 01, 02 and 03 would be similarly wired in one of the above ways.

Whether the coil 22 is connected in series or in parallel depends on the application of the motor 10 and the available power supply. In a situation where a high voltage, low current power source is available the coil 22 ordinarily would be wired in series to minimize power losses across the coil. In a low voltage, high current situation ordinarily it would be desirable to wire the coil in parallel to provide the appropriate potential difference across a coil segment.

When wired in either configuration, a magnetic field will result around the coil winding 22 when a current is applied. As current flows through each turn of the coil 22, a magnetic field is created. The fields of the closely spaced turns merge together to create a cumulative magnetic field having opposite poles at either end of the phase segment.

The coil winding 22 for three phases is shown in FIG. 10 looking down onto the top of the wound form 62 relative to the illustration of FIG. 7 without the circuit connections described above. The coil winding 22 has coil phases 01, 02 and 03, each of which is composed of coil segments A₁, B₁, C₁; A₂, B₂, C₂; and A₃, B₃, C₃, respectively. Each of the respective coil segments, such as the coil segment A_n, or the coil segment B_n, etc., has a length L_{Rn} and a height L_{Rn} . The space between each coil segment is L_{Rn} and the space between adjacent coil phases (a coil phase is the assembly of coil segments A_n, B_n, etc. forming such coil phase, such as the first phase 01) is approximately L_{Rn} . In some applications the space between adjacent coil phases may be less than L_{Rn} to provide an overlap between the wrapped coil phases and to improve torque characteristics of some motors, for example, depending on the application of the motor 10, as is known. If desired, the coil 22 on the form 62 (or after it has been removed from the form 62) may be coated with a thermally conductive, electrically insulating material such as an insulating varnish which will loosely hold the wiring of the coil segments together.

The next step in making the coil winding 22 is to deform the winding at least partly to flatten it so that the coil segments which make up respective coil phases can be wrapped in a circumferential fashion described below. Accordingly, relative to the illustration of FIG. 10, the coil winding 22 is collapsed in the width dimension of the winding form 62 by rotating the bottom corners 63a, 63b of coil segment A₁, 64a, 64b of coil segment B₁, etc. of the coil winding 22 counterclock-

wise. Partially rotated and collapsed coil winding 22 and form 62 are shown in FIG. 11. At this point the partially collapsed form 62 preferably is removed from within the coil winding 22. However, if the coil winding 22 has adequate dimensional integrity, the form 62 may be removed prior to the collapsing step.

The corners 63a, 63b, etc. are rotated a total of approximately 90 degrees, thus substantially fully flattening the coil 22. This fills in the empty spaces originally between adjacent coil segments and thus provides coil segments that have a segment length of two times L_{Rn} . The effect of this collapsing action is to create a coil winding 22 with coil phases that have an alternating magnetic polarity across each distance L_{Rn} when electrically energized. The flattened coil 22 may then be coated or re-coated with a varnish or similar material which will maintain the dimensions of the coil and may also facilitate thermal conduction.

The just described collapsing action is analogous to the relative movement of two opposite flat surfaces of a parallelogram undergoing relative shear. As those surfaces move in opposite directions, the parallelogram collapses, thus bringing the planes of those two surfaces closer together and ultimately to a coplanar relation. If the parallelogram is a square, then upon full collapse the two mentioned opposite surfaces will be substantially coplanar and one pair of originally diagonally related corners, e.g. corners 63a, 63d of FIG. 11, will orient in adjacent relationship. Similarly, with reference to FIG. 11, as the multiple parallelograms formed by the coil segments A₁, B₁, etc. collapse, a pair of corners such as corner 63b and corner 64c of sequential coil segments meet in adjacent substantially coplanar relationship, as is depicted in FIG. 12.

The finished coil 22 is then wrapped around a cylindrical core 66, as is shown in FIG. 12, with an outer dimension sufficient to allow the rotor assembly 12 to rotate freely within the wrapped coil winding 22. The first coil phase 01, still having a length of six times L_{R1} even after having been collapsed, is intended to wrap around the core 66 exactly once. Since there is an unfilled space having a length of L_{R2} between the first coil phase 01 and the second coil phase 02, the second coil phase will have its first coil segment A₂ offset from the first coil segment A₁ of coil phase 01 by one magnet pole face minus any desired overlap, as is shown in FIG. 13. The same applies for the third coil phase 03 which, when wrapped around the core 66, will be offset from the second coil phase 02 by one magnet pole face.

This illustrates the need for the second and third coil phases 02, 03 to have a larger width and segment length, L_{Rn} , than the preceding coil phase. When the second coil phase 02 is wrapped it must be long enough to cover not only the circumference of the core 66 but also the increased circumference attributable to the first coil phase 01. Similarly, the third coil phase 03 must have a length sufficient that it will wrap completely around the core 66, the first coil phase 01 and the second coil phase 02. The increased dimensions of L_{R2} and L_{R3} allows the phase segments, A_n, B_n and C_n, of the second and third coil phases 02 and 03, respectively, to cover the arcuate length of each magnet pole face at the increased diameter, as is shown in FIG. 14.

If the torque requirements of the motor necessitate more coil turns, further sets of coil phase windings are wound upon the core 66 and the preceding set or sets. As above, the coil phases of each further set would consequently have an increased segment length and

width dimension L_{Rn} to accommodate the increasing distance from the magnet pole face. Each coil phase would be electrically connected in the same way as its corresponding coil phase in the first set as described above.

In an alternate embodiment of the invention the winding form 62 may have a hexagonal cross section, as is shown in FIG. 15. In this embodiment a coil winding 22 is produced which will come to a point at the midpoint of each of its widths. When collapsed, this coil configuration tends to lay flatter than the rectangular coil and thus may allow more coil turns to be placed in the air gap 25 of the motor 10. Similarly, other geometric configurations can be employed which would tend to promote a coil winding which can be collapsed flat and easily wound.

After the coil winding is in place and secured together by a further coating of varnish, by drying of a previous coating, by the stiffness of the wire 61 itself, or by some other means, the coil 22 is secured within the previously formed, assembled, wound, etc. field backiron 24 such as by potting. The cylindrical core 66 is removed before or after placing the coil winding 22 in the space circumscribed by the field backiron 24. Alternatively, the field backiron 24 may be wound directly upon the completed coil winding 22, thus allowing flexibility in the dimensional tolerances of the field backiron and coil winding.

A particular advantage of the winding configurations described above over many recently proposed winding configurations is that the winding process can be performed using conventional winding machines and thus can be accomplished inexpensively. The winding configuration of the present invention also provides a denser packing of electrical conductor turns in the air gap 25 than is possible with many conventional windings, thus permitting more coil turns in the same area and a stronger stator magnetic field.

To establish the magnetic field in the stator 14 that is necessary to drive the rotor 12, the completed field winding 22 is electrically connected as in the manner shown in FIGS. 16 and 17. The components surrounded by the dashed line in FIG. 16 constitute the electronics package 78 for the motor 10. The other components are the separate coil phases 01, 02 and 03 of the coil winding 22 connected in a conventional Wye commutation configuration 80 for a three phase motor.

While the field winding and commutation circuit are configured for use in a three phase motor, one with ordinary skill in the art will appreciate that the invention may be employed in any polyphase motor with similar results.

The electronics package 78 illustrated in FIG. 16 preferably may be mounted directly in the motor housing 26, e.g. being formed and/or constructed on the printed circuit board 44. The electronics package includes power circuitry 82 for providing unfiltered full wave rectified power from an alternating current power source 84; commutation and power transistors 86 for controlling current flow to and between each of the coil phases 01, 02 and 03; position sensors 88 for determining the rotor shaft 16 angular position; an integrated circuit 90 for controlling the commutation and power transistors 86; and a power conditioning circuit 92 for supplying 12 volt direct current power to the position sensors 88 and the integrated circuit 90. The power circuitry 82 is a conventional rectifying circuit composed of four diodes D₁, D₂, D₃ and D₄. The conditioning circuit 92

is also a conventional circuit for converting rectified alternating current into 12 volt direct current.

The integrated circuit 90 uses standard logic elements available from custom IC manufacturers combined to provide the functions which will be discussed herein. Given the discussion below of the inputs, outputs and required functions of the integrated circuit, one skilled in the art could design the physical IC with reasonable effort. If desired, those functions alternatively may be carried out by discrete components, but in such case the size of the electronics package 78 may become too large for mounting within the motor housing 26.

The integrated circuit 90 has several outputs, including three drivers, DRIVE 1, DRIVE 2 and DRIVE 3, to switch the commutation transistors Q1, Q2, and Q3; a switch driver PWM PWR, which preferably is pulse width modulated, to drive the power transistor QP; a common/power ground reference, COMMON; and a 12 volt DC SUPPLY CONTROL. The integrated circuit 90 has several inputs, including a 12 volt DC power input; three input signals from the position sensors 88; an INHIBIT signal that may be used to latch the commutation transistors, Q1, Q2, Q3 and the power transistor QP in the nonconducting state such that the motor will not run even if power is applied to the power supply 84; and a number of motor control inputs, for example for speed, direction and power control purposes.

The motor control inputs are COMMON, FORWARD/REVERSE, SPEED, PHASE ADVANCE, and LOW SPEED LEVEL ADJUST. All of these signals are at low power signal logic level. FORWARD/REVERSE is accomplished by opening or shorting the signal to COMMON. This can be accomplished internal to the motor for a fixed direction, clockwise/counterclockwise, application or via an external contact for reversing motor applications. SPEED is provided via an external variable resistance between the speed tap and signal common to provide for variable speed through pulse width modulation of commutation power as is discussed below. PHASE ADVANCE is an input from an external or internal resistor to allow adjustment of the phase to improve high speed operation. LOW SPEED LEVEL ADJUST is an input from an external or an internal fixed resistor between COMMON and LOW SPEED LEVEL ADJUST to fix the maximum speed of the motor. Three additional inputs, RAMP, LINEAR and EXPONENTIAL, provide a ramp, linear, or exponential function acceleration, respectively, for specialized motor applications. All of these inputs are low level logic signals from external inputs.

The integrated circuit 90 processes the motor control low level logic signal inputs to determine the characteristics of the output signals described above. For example, the integrated circuit 90 processes the input signal LOW SPEED LEVEL ADJUST to determine the maximum duty cycle of pulse width modulated output PWM PWR which drives the power transistor QP.

Commutation of the coil phases 01, 02, and 03 is explained with respect to FIGS. 16-18. Each coil phase 01, 02 and 03 is connected to ground through a commutation transistor, Q1, Q2 and Q3, respectively. Power is supplied to the coil Wye circuit 80 through the power transistor QP. In FIG. 17 the commutation transistors Q1, Q2 and Q3 are represented as switches, S1, S2 and S3, respectively, which couple the coil phases 01, 02 and 03 to a source of ground reference potential 94 as controlled by the integrated circuit 90. The power transistor

QP is represented as the switch SP which couples the commutation circuit 80 to unfiltered full wave rectified power also as controlled by the integrated circuit 90.

The position of the rotor 12 relative to the coil phases is detected by three position sensors 88 mounted on the circuit board 44 adjacent the rotor shaft 16 at 120 degree intervals. The position sensors are preferably Hall effect sensors which sense the shaft position by sensing the rotational position of a ring magnet 95 (shown in FIG. 1) on the rotor shaft 16. Alternatively, the position sensors may be photodiodes which detect shaft position by reflecting light off of a reflective surface of the shaft 16, or other equivalent position sensing devices. The outputs of the position sensors are coupled to the integrated circuit 90 via lines 96, 97 and 98 which determines from those signals whether to open or to close the switches SP, S1, S2 and S3. FIG. 18 illustrates the desired state that the switches SP, S1, S2 and S3 should assume as a function of the position of the rotor shaft 16. The vertical axis in FIG. 18 represents the state of the switches with the higher signal indicating that the switch is closed and a lower signal indicating that the switch is open. The horizontal axis represents the angular position of the rotor shaft 16 with the length of the axis totaling approximately two revolutions or 720 degrees for illustrative purposes.

When the rotor is at rest, the integrated circuit 90 uses the shaft position information obtained from the position sensors 88 along with the FORWARD/REVERSE motor control input to determine which coil phase to energize first to begin rotation of the rotor. Commutation sequencing i.e., 01, 02, 03, 01 etc. or 03, 02, 01, 03 etc. is determined from the level or sign of the FORWARD/REVERSE input to produce the desired directional rotation (clockwise/counterclockwise).

The commutation circuit 80 is controlled through the commutation and power transistors 86 by the integrated circuit 90 in the manner illustrated in the commutation logic table below (Table 1). In the table a numeral '1' represents a switch in the closed, or conducting position and a numeral '0' represents an open or nonconducting switch.

COMMUTATION LOGIC TABLE						
	01	01	02	02	03	03
SP	0	1	0	1	0	1
S1	1	1	1	0	0	0
S2	0	0	1	1	1	0
S3	1	0	0	0	1	1

As can be seen from Table 1, each commutation phase 01, 02 and 03 has an ON and an OFF cycle corresponding to whether the power switch SP is supplying current to that coil phase. Assuming the motor 10 is running with power supplied to coil phase 03 with SP and S3 closed, as the rotor reaches a certain angular position, the power switch SP is opened and switch S1 is closed (see column 1 of Table 1). With S1 closed, the residual power stored in coil phase 03 flows to coil phase 01 when S3 is opened. This begins energizing coil phase 01 with residual energy from coil phase 03 which conventionally would have been dissipated in a bypass device as heat. Since switch S1 is closed just prior to S3 being opened, the inductive spike is also eliminated by allowing the current to flow from coil phase 03 to coil phase 01. The power switch SP is then closed allowing

current to flow to coil phase 01 to completely energize it (Table 1, Col. 2). The magnetic field thus created in energized coil phase 01 interacts with the pole-to-pole magnetic field of the rotor 12, thus producing a reactant torque which rotates the rotor an angular distance of approximately two pole faces or 120 degrees.

Subsequently, the power switch SP is opened disabling current flow to the commutation circuit and switch S2 is closed (Col. 3). When switch S1 is opened, residual energy stored in previously energized coil phase 01 will then flow to coil phase 02 beginning its activated stage. When the power switch SP is again closed, the coil phase 02 will be energized creating a magnetic field and causing the rotor 12 to rotate another 120 degrees (Col. 4). The power switch SP is then opened, S3 closed and S2 opened to energize coil phase 03 with the residual power from coil phase 02 (Col. 5). When power is again applied (Col. 6), coil phase 03 will also create a magnetic field which interacts with the pole-to-pole magnetic field of the rotor 12 to complete one 360 degree rotation of the rotor. This sequence is repeated continuously to provide commutative power to the motor 10.

The power switch SP is closed allowing current to flow to the next sequential coil phase, as described above, at the same time as the commutation switch from the previously energized coil phase is opened or soon thereafter, as determined by the rotational position of the shaft. Alternatively, the potential voltage between the commutation circuit juncture 99 and power supply 84 can be measured, and the power switch SP closed when the potential difference reaches approximately zero.

The commutation circuit described above is actually accomplished in the transistors Q1, Q2 and Q3. When shaft position signals 96, 97, 98 received by the IC 90 indicates the coil phase 01 is to be conducting to ground 94 (switch S1 in FIG. 17 closed) a high or active signal is output from DRIVE 1 over Line 100 to the transistor Q1. This drives the Q1 transistor and grounds Line 102 which is connected to coil phase 01, thus allowing current to flow through coil phase 01. Switching for the other coil phases 02 and 03 is performed in the same manner with transistors Q2 and Q3, respectively. Current is supplied to the coil phases over line 104 by the transistor QP when the IC 90 drives PWM PWR (line 106) to a low or inactive state.

The speed at which the rotor 12 will rotate may be determined by the average power applied to the coil phases 01, 02, 03 over a period of rotation. The motor speed is a function of a variable or fixed signal input, e.g. which may be determined by the application in which the motor is used; and that signal is provided to the integrated circuit 90 at the input SPEED. Average power to the coil phases may be determined or controlled by pulse width modulating the power supplied to the coil phases by the power transistor QP. Based on the signal supplied to the SPEED input of the integrated circuit 90, the integrated circuit determines the pulse width of the pulse width modulated signal PWM PWR which in turn drives the power transistor QP. As a result, the commutation circuit 80 is actually powered by pulse width modulated power, as shown in FIG. 19. The basic chop frequency of the PWM PWR signal from the integrated circuit 90 is preferably in the range of 20-30 Kilohertz (Khz) although higher or lower frequencies may be employed. The 20-30 Khz chop frequency is at least a decade higher than other system

time constraints and thus simulates an essentially constant power input to the commutation circuit 80.

The percentage of the chop frequency duration during which power is applied determines the average power supplied to the commutation circuit 80. The uppermost signal in FIG. 19 represents an exemplary signal in which power is applied during 20 percent of the chop frequency, thus resulting in a 20 percent duty cycle. As a result, the motor 10 will operate at 20 percent of its maximum speed. The middle and lower signals represent exemplary duty cycles of 50 and 80 percent, respectively. In the preferred embodiment the speed of the motor may vary continuously between a minimum and maximum value by varying the duty cycle of the power to the commutation circuit 80.

The motor may also be configured to operate interchangeably with an alternating current (AC) or direct current (DC) power supply. To produce the same output torque at the same speed for different power supplies, i.e., AC and DC, the field winding 22 may be configured as shown in FIG. 20. For a $\frac{1}{4}$ horsepower motor an AC power requirement would be on the order of approximately 115 VAC at 2 amps while a DC power requirement to produce the same horsepower would be approximately 12 VDC at 18.5 amps. Consequently, to have the same output torque, which as discussed previously is a function of the number of coil turns and the applied current, each phase of the commutation circuit 80 must have two sets of windings, one for AC power and one for DC power. (The AC coils are denoted as X_n and the DC coils are denoted as Y_n .)

The commutation circuit is again configured as a Wye with each coil phase 01, 02 and 03 having two respective switching elements SA, SB and a respective commutation transistor Q1, Q2, Q3. When configured to operate on direct current, as shown in FIG. 20, switch SB is open and switch SA is in position to bypass the AC coil set X_n . DC power thus will flow only through the DC coil set Y_n which is generally wound of a lower gauge wire than the AC coil set X_n to handle the higher DC amperage. Power flow bypasses the AC coil set through the line 110. When configured to operate on AC power, the switch SB is closed (not shown) and the switch SA is in position to cooperate with switch SB to conduct current through the AC coil set X_n . Alternating current will then flow through both the AC coil set X_n and the DC coil set Y_n .

When configured to operate on DC power, the power conditioning circuit 92 is bypassed, thus allowing 12 volt DC power to be supplied to the integrated circuit 90 and the position sensors 88.

In either the AC or DC configuration current flow to the commutation circuit is regulated by the power transistor QP as controlled by the integrated circuit 90. The power supplied to the power transistor QP is determined by switch SM which may be positioned to supply power from the unfiltered, full wave rectified AC power supply 112 or the DC power supply 114. Preferably the action of the switches SA and SB are coupled to the switch SM so that the former will automatically configure to the AC or DC power configuration depending on the position of switch SM. The switch SM may be external to the motor to allow manipulation by a user or internal and manipulated such as by insertion of a power supply or power supply cord.

It will be appreciated by one of ordinary skill in the art that although the features of the invention are described above with respect to an electromechanical

15

device in the form of a slotless, brushless, large air-gap electric motor, many of the features may be used in conjunction with other motors, generators and similar electrical and electromechanical devices. For example, the commutation scheme described herein could be used in a typical slotted, brushless motor and the magnetically permeable flux shorting elements could be employed in many motors equivalent devices that establish a rotating magnetic field, to name but a few.

What is claimed is:

1. A method of making a field winding for an electrical motor having a stator and a permanent magnet rotor, comprising the steps of:

spirally winding a wire around a polygonal shaped form in a plurality of coil segments, each coil segment having a length corresponding to an arcuate length of a pole face of the permanent magnet rotor;

leaving unwound spaces between said coil segments, said spaces having a length substantially equal to the length of one of said coil segments;

collapsing opposite sides of said form so that portions of said coil segments fill said spaces substantially flattening said wire winding; and

forming said flattened winding into a hollow cylinder to form the field winding.

2. The method of claim 1, further including the step of electrically connecting said coil segments in series.

3. The method of claim 1, further including the step of electrically connecting said coil segments in parallel.

4. The method of claim 1, further including the step of electrically connecting said coil segments to form a Wye junction.

5. The method of claim 1, further including the step of coating said flattened winding with material to secure said flattened winding together.

6. The method of claim 1, wherein said step of forming includes wrapping said flattened winding around a cylindrical core.

7. The method of claim 6, further including the step of winding a magnetically permeable material around said field winding to form a field backiron surrounding said field winding.

8. The method of claim 1, wherein sections of said coil segments producing an active magnetic field are parallel to an axis of rotation of the rotor.

9. The method of claim 1, wherein portions of said coil segments are at substantially an equal distance relative to the axis of rotation of the rotor.

10. A method of making a field winding for an electrical motor having a stator and a permanent magnet rotor, comprising the steps of:

spirally winding a wire around a polygonal shaped form in a plurality of coil segments, the number of

16

said coil segments corresponding to a number of pole pairs of said rotor;

leaving unwound spaces between said coil segments, said spaces having a length substantially equal to the length of one of said coil segments;

collapsing two opposite sides of said form so that portions of said coil segments fill said spaces substantially flattening said wire winding; and

forming said flattened winding into a hollow cylinder to form the field winding.

11. The method of claim 10, wherein the number of said coil segments is equal to the number of said pole pairs times the number of phases of the motor.

12. The method of claim 10, further including the step of electrically connecting said coil segments in series.

13. The method of claim 10, further including the step of electrically connecting said coil segments in parallel.

14. The method of claims 10, further including the step of electrically connecting said coil segments to form a Wye junction.

15. The method of claim 10, further including the step of coating said flattened winding with material to secure said flattened winding together.

16. The method of claim 10, wherein said step of forming includes wrapping said flattened winding around a cylindrical core.

17. The method of claim 16, further including the step of winding a magnetically permeable material around said field winding to form a field backiron surrounding said field winding.

18. The method of claim 10, wherein sections of said coil segments producing an active magnetic field are parallel to an axis of rotation of the rotor.

19. The method of claim 10, wherein sections of said coil segments are at substantially an equal distance relative to the axis of rotation of the rotor.

20. A method of making a polyphase field winding for an electrical motor having a stator and a permanent magnet rotor, comprising the steps of:

spirally winding a wire around a polygonal shaped form in a plurality of coil segments, at least one dimension of the cross-section of said form being different for coil segments corresponding to different phases of the field winding;

leaving unwound spaces between said coil segments, said spaces having a length substantially equal to the length of one of said coil segments;

collapsing two opposite sides of said form so that portions of said coil segments fill said spaces substantially flattening said wire winding; and

forming said flattened winding into a hollow cylinder to form the field winding.

* * * * *